

AD-A252 783



R&D 5824-AN-01 ^②

CRANFIELD INSTITUTE OF TECHNOLOGY


RADIAL INFLOW TURBINE STUDY

SEVENTH INTERIM REPORT

by

Dr S Hamid
Prof R L Elder

MARCH 1992



United States Army

EUROPEAN RESEARCH OFFICE OF THE US ARMY

London England

CONTRACT NUMBER: DAJA45-89-C-0006
CRANFIELD REFERENCE: 06/769E

PROJECT START DATE: 1st January 1989
PROJECT COMPLETION DATE: 30th June 1993

Department of Turbomachinery & Engineering Mechanics
School of Mechanical Engineering
Cranfield Institute of Technology
Cranfield, Bedford, MK43 0AL

Approved for Public Release; distribution unlimited

92-18156



92 7 10

041

SECURITY CLASSIFICATION OF THIS PAGE

REPORT DOCUMENTATION PAGE

Form Approved
OMB No. 0704-0188

1a. REPORT SECURITY CLASSIFICATION Unclassified			1b. RESTRICTIVE MARKINGS	
2a. SECURITY CLASSIFICATION AUTHORITY			3. DISTRIBUTION/AVAILABILITY OF REPORT Distribution unlimited	
2b. DECLASSIFICATION/DOWNGRADING SCHEDULE				
4. PERFORMING ORGANIZATION REPORT NUMBER(S) 06/769E(7)			5. MONITORING ORGANIZATION REPORT NUMBER(S)	
6a. NAME OF PERFORMING ORGANIZATION Cranfield Institute of Technology		6b. OFFICE SYMBOL (If applicable)	7a. NAME OF MONITORING ORGANIZATION European Research Office	
6c. ADDRESS (City, State, and ZIP Code) Cranfield, Bedford, MK43 OAL			7b. ADDRESS (City, State, and ZIP Code) 223 Old Marylebone London NW1 5TH	
8a. NAME OF FUNDING/SPONSORING ORGANIZATION USACCE - RCO Burtonwood		8b. OFFICE SYMBOL (If applicable)	9. PROCUREMENT INSTRUMENT IDENTIFICATION NUMBER R & D 5824-AN-01	
8c. ADDRESS (City, State, and ZIP Code) HQ 47th Area Support Group Burtonwood Road, Great Sankey Warrington, Cheshire, WA5 1UN			10. SOURCE OF FUNDING NUMBERS PROGRAM ELEMENT NO. PROJECT NO. TASK NO. WORK UNIT ACCESSION NO.	
11. TITLE (Include Security Classification) Radial Inflow Turbine Study				
12. PERSONAL AUTHOR(S) Dr S Hamid - Professor R L Elder				
13a. TYPE OF REPORT INTERIM		13b. TIME COVERED FROM 1.1.92 TO 29.2.92	14. DATE OF REPORT (Year, Month, Day) March 1992	15. PAGE COUNT 11
16. SUPPLEMENTARY NOTATION R7-8.40/IH				
17. COSATI CODES FIELD GROUP SUB-GROUP			18. SUBJECT TERMS (Continue on reverse if necessary and identify by block number) Radial Turbines Laser Anemometry	
19. ABSTRACT (Continue on reverse if necessary and identify by block number) <p>The radial inflow turbine is a primary component used both in small gas turbines and turbochargers. Better understanding of the flow processes occurring within the small passages of the machine could well result in the improved design of units. As most of the detailed aerodynamics is still ill-defined, a joint research project with the objective of improving our understanding has been instigated by Cranfield, the US Army and Turbomach (San Diego).</p> <p>This document gives the seventh report on the project and describes progress and measurements taken.</p>				
20. DISTRIBUTION/AVAILABILITY OF ABSTRACT <input type="checkbox"/> UNCLASSIFIED/UNLIMITED <input type="checkbox"/> SAME AS RPT. <input type="checkbox"/> DTIC USERS			21. ABSTRACT SECURITY CLASSIFICATION	
22a. NAME OF RESPONSIBLE INDIVIDUAL			22b. TELEPHONE (Include Area Code)	22c. OFFICE SYMBOL

PROGRESS REPORT

PERIOD: 1.1.92 TO 29.2.92

As discussed in the last report, laser anemometry measurements are now under progress at various positions downstream of the rotor. The original design of both optical windows A and B (fig 1) had to be modified to overcome several unforeseen problems which occurred while the rig was operating.

Previous reports explain the problems caused by the icing of the window due to sub zero temperatures at the turbine outlet. This problem was solved by installation of electrical heaters at the turbine inlet far enough upstream not to disturb the flow. It was possible to maintain the turbine outlet temperature reasonably high so avoiding any condensation on the windows.

Measurements at Window A

Laser anemometry results for the following running conditions have been obtained:

$U/V = .64, .68, .70, .72$ with $PR = 3.0$

$U/V = .64, .68, .70$ with $PR = 3.5$

Fifteen radial stations were selected to perform laser measurements at window A, fig 1. The separation between two stations was .125 inch (3.2mm). Laser measurements provided the velocity, flow angle and turbulent intensities at all measurement positions. In order to compare the laser results, a Cobra yawmeter probe has also been used after it was calibrated in a windtunnel (the details of which have already been included in previous reports). Cobra probe measurements were taken at approximately the same radial positions as the laser measurements.

Figs 2 and 3 give the laser anemometry and pressure probe results for pressure ratios of 3.0 at $U/V = .64$. Fig 2 gives the velocity variation along the radius of the duct at window A whereas fig 3 shows the swirl angle variation for different radial positions. Figs 4 and 5 show the results for the same window but at a different running condition ($U/V = .64$, $PR = 3.5$). Results for all the other running conditions have now been completed which will be presented in the final report.

Measurements at window B

Results at the following conditions have now been completed for this window:

$U/V = .64, .68, .70, .72$; $PR = 3.0$

$U/V = .64, .68, .70$; $PR = 3.5$

Ten radial stations with a separation of 3.2mm were chosen in this case. Cobra probe results for all those positions have also been obtained.

Figs 6 and 7 give a comparison of laser anemometry measurements with those obtained by the Cobra probe for the same running conditions ($U/V = .64$, $PR = 3.0$) and approximately at the same radial positions. Results for the other running conditions have also been completed. Discussions on these results will be included in the final report.

Measurement at the Inlet of the Turbine Rotor

It was also reported in the previous report that several schemes were under consideration to provide optical access for laser measurements at various positions at the turbine rotor inlet (between guide vanes and rotor). This task has been time consuming but is now completed. The details of the machining and the various positions at the inlet have not been given in this report and will be explained in the next report. Mirrors and optical windows suitable for this work have been obtained and the laser results will be undertaken in the near future.

R7-8.40/IH

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
by	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A-1	



FIG 1 ; WINDOWS FOR OPTICAL ACCESS

CRANFIELD LA MEASUREMENTS

Window A : PR = 3.0 : $U/V = .64$




Figure 2

CRANFIELD LA MEASUREMENTS

Window A : $PR = 3.0$: $U/V = .64$





Figure 3

CRANFIELD LA MEASUREMENTS

Window A : PR = 3.5 : U/V = .64



• Cobra + Laser

Figure 4

CRANFIELD LA MEASUREMENTS

Window A : $PR = 3.5$: $U/V = .64$




Figure 5

CRANFIELD LA MEASUREMENTS

Window B : $PR \approx 3.0$: $U/V = .64$




Figure 6

CRANFIELD LA MEASUREMENTS

Window B : $PR = 3.0$: $U/V = .64$




Figure 7